



Sample Tire Assessment Report

Anthony, TX[#447]

Unit inspection #: 21717

[#11291] 03/14/2018

Fleet: RETAIL

Vehicle #: 405956

VIR:500 - Vehicle with no Apparent Problems

Driver:



77785012555326

[VIN: 4V4NC9EJ0FN909746]

Vehicle Type: 6X4 LAYOUT 107



Tire Position		Product	Inspection Status
		Generic Size/XX/XXXXXX 0	302-Inspected Normal
LF	RF	[11] No Action. Flag Only.	TIR
		Generic Size/XX/XXXXXX 0	302-Inspected Normal
LFO	LFI	[11] No Action. Flag Only.	TIR
RFI	RFO	Generic Size/XX/XXXXXX 0	302-Inspected Normal
		[11] No Action. Flag Only.	TIR
		Generic Size/XX/XXXXXX 0	302-Inspected Normal 402-Flagged as Flat [System] 401-Check Air Pres. [System]
LRO	LRI	[15] Replace Tire	TIR
RRI	RRO	Generic Size/XX/XXXXXX 0	302-Inspected Normal
		[11] No Action. Flag Only.	TIR
		Generic Size/XX/XXXXXX 0	302-Inspected Normal
		[11] No Action. Flag Only.	TIR

- = Matched
- ≠ Mismatched
- ? Not verified
- OK OK
- Warning Warning
- Immediate action required Immediate action required

Notes

